


REPORT NO: BCNR33-XXXXXX

1995 NISSAN SKYLINE GT-R (SAMPLE)

Report generated on 2020-04-04

VEHICLE DETAILS

VEHICLE DETAILS		GRADE
Data Source		GR/
Reported date		The J Japa simila
Lot number		51111
Chassis ID	BCNR33-XXXXXX	
Make	NISSAN	
Model	SKYLINE	*
Mileage		
Engine CC	2600	(
Year	1995	
Grade	GT-R	-
Inspection	N/A	•
Equipment	AAC	
Transmission	F5	
Start price	¥330,000	
Finish price		Ţ
Color	PURPLE	Auc
Condition	3	•
Status	Sold	Vehi
		•



	3 Poor condition	
	Accident / Repair Repair history found	•
Ĵ	Mileage report High mileage	×
5	Use history Private Car	Ø
	Stolen check	



Ш

No stolen status

Διια	tion grade
Aut	
0	Poor condition / noticeable dents & damage / rust / past repair

Vehicle use as a private car

NOTE: This Autocheck Vehicle History Report is based only on Information supplied to Autocheck CO. and available as of 2020-04-04 08:45:25. Other information about this vehicle, including problems, may not have been reported to Autocheck CO. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next Japanese used car.

HISTORY RECORDS (JAPAN)

Type of record	Reported event	Reported date	Source	Details	Airbag
Accident/Repair	Reported				
Malfunction	Vot reported				
Theft	Vot reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

REPORTED ODOMETER HISTORY






Use in the contaminated regions ⁴	Radioactive contamination test fail ${}^{\scriptscriptstyle 5}$	Commercial use
Not reported	Not reported	Not reported

MANUFACTURE RECALL HISTORY

Date	Source	Affected part	Details

No records found.

AUCTION SHEETS & PHOTOS



Please proceed to the next page to see English Translation of this auction sheet.

AUCTION SHEET ENGLISH TRANSLATION

Auction No.	Vehicle Use		Displacement	Grade	Grade	
	Private		2600	GT-R	3	
6027	Japan Y/M	Make/model	Model code	Door Style	Exterior	Interior
	1995/3	SKYLINE	E-BCNR33	4D	С	C

Current Inspection (Year/month)		Transmission	Sun roof	alloy wheel	power steering	power window	
N/A		F5	-	1	1	1	
Mileage in Kms		Air condition	Leather	TV/Navi	ABS	Airbag	
		AAC	-	-	-	1	
original color	change color	color no:	Recycling deposit	Sales point			
PURPLE		2P2	¥10,980	* Muffler			
Fuel Interior color			* Alloy w	heels			
GS (Gasoline) Black			* ETC				
Seats	Drive type	Drive					
5	2WD	RHD					
Notice		Registration number		N/A	١		
Underbody rust			Chassis number		1.1.1	laters.	
Underbody rus	St		Chassis number				

A2 Scratch

С

S

U

AU

W

B2-3 Large Dents

Rust

Dent

Corrosion

Scratch & Dent

Repair History

Part exchange history

Top-Class

No Inspection

Inspector Report

Small scratches on the Sheets


Front buffer A3

Hood repair mark W2

- Roof paint mark
- Right door replaced XX
- Right skirting replaced XX
- Fron right side repair mark W3
- Rear left side paint mark
- Scratches on the exterior A1

Rear buffer A2

Length	Width	Height	Х	
397	169	140	XX	



*Please proceed to the next page to see the full auction list explanation.

CONDITION SHEET EXPLANATION

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- B Dent with scratch

B1 Distortion on (radiator) core support or back panel (approximately size of a thumb)

B2 Big Distortion on (radiator) core support or back panel

B1-B4 Large dents

- C1 Corrosion
- C2 Heavy Corrosion
- AU2 Dent and Scratch (Medium).
- E1 Few Dimples
- E2 Several Dimples
- E3 Many Dimples
- G Stone chip in glass
- **H** Paint faded or (Thumb size hole from rust, corrosion or rotting)
- P Paint damaged marked

- S1 Rust
- S2 Heavy Rust
- **U1** Small Dent
- U2 Dent
- **U3** Big Dent

Y1 Small Hole or Crack

- Y2 Hole or Crack
- Y3 Big Hole or Crack

X1 Small Crack on Windshield (approximately 1cm)

R Repaired Crack on Windshield

RX Repaired Crack on Windshield (needs to be replaced)

- X Needs to be replaced or crack on glass
- XX Replaced
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- W3 Obvious Repair Mark/Wave (needs to be repainted)

AUCTION GRADE EXPLANATION

- 6 / S New car
- 5 Used but appears as new
- 4.5 Very clean with only minor pin dents & scratches
- 4 Good condition with normal wear & tear
- 3.5 Numerous condition faults / possible minor repair

3 Poor condition / noticeable dents & damage / rust / past repair

- 2 Very poor condition / water damaged
- **1** Modified (usually performance parts)

0 Repaired

R Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)

RA Accident repaired, been in crash, parts replaced, generally small damages.

*** Ungraded (existing fault / damage)

A - D Body / interior condition (A – as new, B – very clean, C – average, D – poor)

E – The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty.





** Verified Photos



1 Chassis number: a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

2 Safety grade: Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

3 Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily - not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely - not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export - not qualified for driving in Japan , the vehicle is determined to be exported

4 Use in the contaminated regions: The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

5 Radioactive contamination test: radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

AUTOCHECK.JP DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY AUTOCHECK.JP OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. AUTOCHECK.JP FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 Autocheck Corporation. All rights reserved.