





2003 SUBARU IMPREZA WRX STI (SAMPLE)

Report generated on 2020-03-09

VEHICLE DETAILS

Data Source		
Reported date		
Lot number		
Chassis ID	GDB-XXXXXX	
Make	SUBARU	
Model	IMPREZA WRX	
Mileage		
Engine CC	2000	
Year	2003	
Grade	WRX STI	
Inspection	N/A	
Equipment	AAC	
Transmission	F6	
Start price	¥0	
Finish price	N/A (sold with nego)	
Color	BLUE	
Condition	4	
Status	N/A (sold with nego)	



AUTOCHECK GRADING

Average condition

The Autocheck grading scheme is based on standard Japanese auction grading system. it let's you compare similar vehicles with ease.



Auction grade Average condition



Accident / Repair



No accidents or repairs.

(* hardly noticable minor repair found *)



Mileage report



High mileage



Use history Private/Normal





Stolen check

No stolen status





AUTOCHECK FACTS

Auction grade



Average condition

Mileage & Use history



Private usage

NOTE: This Autocheck Vehicle History Report is based only on Informn supplied to Autocheck CO. and available as of 2020-03-09 13:29:10. Other information about this vehicle, including problems, may not have been reported to Autocheck CO. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next Japanese used car.

✓ HISTORY RECORDS (JAPAN)

Type of record	Reported event	Reported date	Source	Details	Airbag
Accident/Repair	Reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

REPORTED ODOMETER HISTORY

Reported date Kilometres Source


USE HISTORY (JAPAN)		
Use in the contaminated regions ⁴	Radioactive contamination test fail	Commercial use

Not reported Not reported Not reported

MANUFACTURE RECALL HISTORY

Date Source Affected part Details

No records found.



Please proceed to the next page to see English Translation of this auction sheet.

CONDITION SHEET ENGLISH TRANSLATION

Auction No.	Vehicle Use		Displacement	Grade
	Private use		2000 cc	STI
6027	Japan Y/M Make/model		Model code	Door Style
	2003/6	IMPREZA WRX	GH-GDB	4

Grade		
4		
Exterior Interior		
CC		

Current Inspection (Year/month)			
N/A			
Mileage in Kms			
original color	change color	color no:	
BLUE		20	
Fuel Interior color			
Petrol		Black	
Seats	Drive type	Drive	
5	2WD	RHD	
Notice			

Transmission	sunroof	alloy wheel	power steering	power window
F6	-	✓	1	1
Air condition	Leather	ABS	TV/Navi	Airbag
AAC	-	-	-	1
Recycling deposit	Sales point			
¥2,990	*FIRST TIME AUCTION*			
	Navigation - Digital TV			
	Back monitor - ETC			
Registration		A factor	between	
Chassis number		A factor	between	

*Chapter 1

HID light

MD or CD changer/TV

ETC

Inspector Report

Small scratches

Cigarette burned holes on the Carpet

Under the Bumper (A)

Rear bumper under (A)

Outside AW studless tires

R Sport*



B Large Dent

G Stone chip in glass

S Rust

U Dent


AU Scratch & Dent

W2 Repair History (Repair Mark/Wave)

P/V Paint damaged marked

XX Part exchange history

Length	Width	Height
-	-	-



CONDITION SHEET EXPLANATION

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- **B** Dent with scratch
- **B1** Distortion on (radiator) core support or back panel (approximately size of a thumb)
- **B2** Big Distortion on (radiator) core support or back panel
- **B1-B4** Large dents
- C1 Corrosion
- C2 Heavy Corrosion
- AU2 Dent and Scratch (Medium).
- **E1** Few Dimples
- **E2** Several Dimples
- E3 Many Dimples
- **G** Stone chip in glass
- **H** Paint faded or (Thumb size hole from rust, corrosion or rotting)
- P Paint damaged marked

- S1 Rust
- **S2** Heavy Rust
- **U1** Small Dent
- U2 Dent
- U3 Big Dent
- Y1 Small Hole or Crack
- Y2 Hole or Crack
- Y3 Big Hole or Crack
- **X1** Small Crack on Windshield (approximately 1cm)
- R Repaired Crack on Windshield
- **RX** Repaired Crack on Windshield (needs to be replaced)
- X Needs to be replaced or crack on glass
- **XX** Replaced
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- W3 Obvious Repair Mark/Wave (needs to be repainted)

AUCTION GRADE EXPLANATION

- 6 / S New car
- 5 Used but appears as new
- 4.5 Very clean with only minor pin dents & scratches
- 4 Good condition with normal wear & tear
- 3.5 Numerous condition faults / possible minor repair
- 3 Poor condition / noticeable dents & damage / rust / past repair
- 2 Very poor condition / water damaged
- 1 Modified (usually performance parts)

- 0 Repaired
- **R** Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)
- **RA** Accident repaired, been in crash, parts replaced, generally small damages.
- *** Ungraded (existing fault / damage)
- A D Body / interior condition (A as new, B very clean, C average, D poor)
- **E** The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty.





** Verified Photos



GLOSSARY

- **1 Chassis number:** a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)
- **2 Safety grade:** Determining the overall collision safety performance evaluation For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

3 Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

- **4 Use in the contaminated regions:** The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.
- **5 Radioactive contamination test:** radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

AUTOCHECK.JP DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY AUTOCHECK.JP OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT.
AUTOCHECK.JP FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.