

2013 VOLKSWAGEN GOLF TSI TREND LINE MEISTER EDITION BMT

Report generated on XX-XX-2020

VEHICLE DETAILS		GRADE 4	AUTOCHECK GRADING
Data Source		4	Average condition
Data recorded date			ading scheme is based on standard grading system. it let's you compare
Lot number		Similar vehicles w	un ease.
Chassis ID	WVWZZZXXXXXXXXXX	A	auction grade
Make	VOLKSWAGEN	4	Average condition
Model	GOLF	A A	Accident / Repair
Mileage		N	lo Problem found
Engine CC	1200	("% N	//ileage report
Year	2013	W G	Good mileage
Grade	TSI TREND LINE MEISTER EDITION BMT		Jse history
Inspection	N/A	P	rivate use
Equipment	AC		Stolen check
Transmission	AT	N	lo stolen status
Start price	¥0		
Finish price		AUTOCH	HECK FACTS
Color	BLACK	Auction grade	
Condition	4	Average Condition	
Status	SOLD	Use History	
		Vehicle use	e as a private car

NOTE: This Autocheck Vehicle History Report is based only on Information supplied to Autocheck CO. and available as of 2020-xx-xx xx:xx:xx. Other information about this vehicle, including problems, may not have been reported to Autocheck CO. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next Japanese used car.



ACCIDENT / REPAIR HISTORY (JAPAN)

Type of record	Reported event	Reported date	Source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

REPORTED ODOMETER HISTORY


Reported date	Kilometres	Source

USE HISTORY (JAPAN)		
Use in the contaminated regions ⁴	Radioactive contamination test fail	Commercial use
Not reported	Not reported	Not reported

MANUFACTURE RECALL HISTORY

Affected part Detail

No recall records found.



Please proceed to the next page to see English Translation of this condition sheet.

CONDITION CHECK ENGLISH TRANSLATION

Auction No.	Vehicle Use		Displacement	Grade
	Pr	ivat car	t car 1200 cc TSI TREND L	
6027	Japan Y/M Make/model Model code		Door Style	
	2013/3	GOLF	DBA-1KCBZ	5

Grade			
4			
Exterior	ior Interior		
С	В		

Current Inspection (Year/month)				
	N/A			
М	Mileage in Kms			
original color	change color	color no:		
BLACK		LC9X		
Fuel Interior color				
GS (Gasoline)		Black		
Seats	Drive type	Drive		
5	2WD	RHD		
Notice				

Transmission	Sun roof	alloy wheel	power steering	power window
At	-	-	1	1
Air condition	Leather	TV/Navi	ABS	Airbag
AC	-	✓	✓	1
Recycling deposit	Sales point			
¥18,140	Outside Navigation			
	TV			
	ETC			
Registration number	N/A			
Chassis number	WVWZZZXXXXXXXXXX			

Inspector Report

Small scraches on exterior A1 Front bumper small scratch Rear bumper small scratch



A3 Large Scratches

S Rust


Dent U


P3 Paint damage mark

W Repair History

X

XX





CONDITION LIST EXPLANATION

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- **B** Dent with scratch
- **B1** Distortion on (radiator) core support or back panel (approximately size of a thumb)
- **B2** Big Distortion on (radiator) core support or back panel
- **B1-B4** Large dents
- C1 Corrosion
- C2 Heavy Corrosion
- AU2 Dent and Scratch (Medium).
- **E1** Few Dimples
- **E2** Several Dimples
- E3 Many Dimples
- **G** Stone chip in glass
- **H** Paint faded or (Thumb size hole from rust, corrosion or rotting)
- P Paint damaged marked

- S1 Rust
- **S2** Heavy Rust
- **U1** Small Dent
- U2 Dent
- U3 Big Dent
- Y1 Small Hole or Crack
- Y2 Hole or Crack
- Y3 Big Hole or Crack
- **X1** Small Crack on Windshield (approximately 1cm)
- R Repaired Crack on Windshield
- **RX** Repaired Crack on Windshield (needs to be replaced)
- X Needs to be replaced or crack on glass
- **XX** Replaced
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- W3 Obvious Repair Mark/Wave (needs to be repainted)

AUCTION GRADE EXPLANATION

- 6/S New car
- 5 Used but appears as new
- 4.5 Very clean with only minor pin dents & scratches
- 4 Good condition with normal wear & tear
- 3.5 Numerous condition faults / possible minor repair
- 3 Poor condition / noticeable dents & damage / rust / past repair
- 2 Very poor condition / water damaged
- 1 Modified (usually performance parts)

- 0 Repaired
- **R** Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)
- **RA** Accident repaired, been in crash, parts replaced, generally small damages.
- *** Ungraded (existing fault / damage)
- A D Body / interior condition (A as new, B very clean, C average, D poor)
- **E** The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty.





** Verified Photos



GLOSSARY

- **1 Chassis number:** a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)
- **2 Safety grade:** Determining the overall collision safety performance evaluation For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

3 Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

- **4 Use in the contaminated regions:** The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.
- **5 Radioactive contamination test:** radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

AUTOCHECK.JP DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY AUTOCHECK.JP OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. AUTOCHECK.JP FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 NEXCA 株式会社. All rights reserved | 神奈川公安委員会許可第452750021276号