

2001 NISSAN SKYLINE GT-R V SPECIFICATIONS2


Report generated on 13-06-XXXX

VEHICLE DETAILS

Auction	AVAILABLE	
Auction date	AVAILABLE	
Lot number	AVAILABLE	
Chassis ID	BNR34-XXX	
Make	NISSAN	
Model	SKYLINE	
Mileage	AVAILABLE	
Engine CC	2600	
Year	2001	
Grade	GT-R V SPECIFICATIONS2	
Inspection	2014/05	
Inspection Equipment	2014/05 ACC PS PW	
Equipment	ACC PS PW	
Equipment Transmission	ACC PS PW	
Equipment Transmission Start price	ACC PS PW F6 ¥2,980,000	
Equipment Transmission Start price Finish price	ACC PS PW F6 ¥2,980,000 AVAILABLE	
Equipment Transmission Start price Finish price Color	ACC PS PW F6 ¥2,980,000 AVAILABLE Black Pearl	

AUTOCHECK GRADING PERFECT CONDITION

The Autocheck grading scheme is based on standard Japanese auction grading system. it let's you compare similar vehicles with ease.





AUTOCHECK FACTS

Auction grade



Perfect condition - Used but appears as new Very clean with only minor pin dents & scratches

Mileage report



Good mileage report

NOTE: This Autocheck Vehicle History Report is based only on Information supplied to Autocheck CO. and available as of XXXX-06-13 10:44:45. Other information about this vehicle, including problems, may not have been reported to Autocheck CO. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next Japanese used car.

AUCTION SHEETS & PHOTOS



Please proceed to the next page to see English Translation of this auction sheet.

AUCTION SHEET ENGLISH TRANSLATION

Auction No
XXX

Vehicle Use		Displacement	Grade
Privat car		2600 cc	GT-R V SPECIFICATIONS2
Japan Y/M	Make/model	Model code	Door Style
2001/05	NISSAN	SKYLINE	2D

Grade		
4.5		
Exterior	Interior	
A	A	

Current Inspection (Year/month)				
2014/05				
М	Mileage in Kms			
Available				
original color	change color	color no:		
Black Pearl		GV1		
Fuel		Interior color		
GS (Gasoline)		Black		
Seats	Drive type	Drive		
2	4WD	RHD		
Notice				

Transmission	Sun roof	alloy wheel	power steering	power window
F6	-	-	✓	1
Air condition	Leather	TV/Navi	ABS	Airbag
AAC	-	✓	-	1
Recycling deposit	Sales point			
¥12,660	One Owner			
	BBS 19" Wheels			
	HKS F-C	Car V Pro		
	HKS EV	Э		
	HKS Kno	ock Amp		
Registration number	AVAILABLE BNR34-XXX			
Chassis number				

Inspector Report

Front Fender W2

Front Bumper small scratch

- A Scratch or crack
- **B** Large Dent
- **C** Corrosion
- **S** Rust
- **U** Dent
- AU Scratch & Dent
- W Repair History

Length	Width	Height	Х
-	-	-	XX

- X Part exchange required
- **XX** Part exchange history

AUCTION LIST EXPLANATION

- A1 Small Scratch
- A2 Scratch
- A3 Big Scratch
- **B1-B4** Large dents
- **E1** Few Dimples
- **E2** Several Dimples
- E3 Many Dimples
- **U1** Small Dent
- U2 Dent
- U3 Big Dent
- W1 Repair Mark/Wave (hardly detectable)
- W2 Repair Mark/Wave
- **W3** Obvious Repair Mark/Wave (needs to be repainted)
- S1 Rust
- **S2** Heavy Rust
- C1 Corrosion

- C2 Heavy Corrosion
- X Need to be replaced
- XX Replaced
- **B1** Distortion on (radiator) core support or back panel (approximately size of a thumb)
- **B2** Big Distortion on (radiator) core support or back panel
- Y1 Small Hole or Crack
- Y2 Hole or Crack
- Y3 Big Hole or Crack
- **X1** Small Crack on Windshield (approximately 1cm)
- R Repaired Crack on Windshield
- **RX** Repaired Crack on Windshield (needs to be replaced)
- X Needs to be replaced
- **B** Dent with scratch
- P Paint damaged marked
- H Paint faded
- G Stone chip in glass

AUCTION GRADE EXPLANATION

- 6/S New car
- 5 Used but appears as new
- **4.5** Very clean with only minor pin dents & scratches
- 4 Good condition with normal wear & tear
- 3.5 Numerous condition faults / possible minor repair
- 3 Poor condition / noticeable dents & damage / rust / past repair
- 2 Very poor condition / water damaged
- 1 Modified (usually performance parts)

- 0 Repaired
- R Repaired (1 small, 2 medium, 3 large)
- RA Repaired (minor)
- *** Ungraded (existing fault / damage)
- A D Body / interior condition (A as new, B very clean, C average, D poor)





** Verified Photos

